

NEMA Stock Motors Wiring Diagrams




FOR 230V







RUN



- Start
- (1) $Y- \triangle START$

- (2) D.O.L
- (3) Soft start







Start

RUN

Part Winding start (4P & 6P Low voltage)


FOR 460V






L2 L3

(2) D.O.L (3) Soft start b. 9 leads




RUN




low voltage (2Y) High voltage (1Y) RUN

B. Single Voltage (460V, 575V, etc.)


a. 3 leads b. 6 leads



D.O.L




Start RUN (1) Y- △ START




(2) D.O.L

(3) Soft start

c. 12 leads 2Δ (For 4, 6P)



RUN Start (1) Part Winding start



Start

RUN

(2) $Y-\triangle$ start